## State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

				<u>,</u>				
System Name Idaho Power-		Idaho Power- Oxbow	•		PWS	/S ID# 4 1 00384		
Month/Year Dec/2021 Entry Po			EP-B, Entry Point for int: Copperfield Park Well Rec		Requ	uired Minimum Residual 0.2 mg/L		
Date	Time	Source(s) i	n use	Lowest free chlorine residual at entry point to distribution system (mg/L)		Notes		
1	0700 Booster Pump			.25				
2	0700	Booster Pump		.26		House 5613	3 .14	
3	0700	Booster Pump		.29		1100000		
4	0700	Booster Pump		.28				
5	0700	Booster Pump		.25				
6	0700	Booster Pump		.26			.14	
7	0700	Booster Pump			.24			
8	0700	Booster Pump		.26				
9	0800	Booster Pump		.25	,	House 5620 .15		
10	1000	Booster Pump		.24	,	110000		
11	1030	Booster Pump		.27				
12	1640	Booster Pump		.27	***************************************			
13	0800	Booster Pump		.22		House 567 .19		
14	0915	Booster Pump		.25		110400 00.		
15	0845	Booster Pump		.22				
16	0815	Booster Pump		.25		House 5613 .18		
17	0900	Booster Pump		.26				
18	0900	Booster Pump		.26				
19	0735	Booster Pump		.26				
20	1400	Booster Pump		.24		House 851 .	14	
21	1145	Booster Pump		.26		110000 001,111		
22	0700	Booster Pump		.23				
23	0930	Booster Pump		.21		House 5620 .12		
24	0700	Booster Pump		.20		110000 0020	, 12	
25	0700	Booster Pump		.20				
26	0700	Booster Pump		.22				
27	0700	Booster Pump		.22		House 567 .13		
28	0800	Booster Pump		.22		110030 001 .	13	
29	0700	Booster Pump		.24		House 5613	. 16	
30	0700	Booster Pump		.25				
31	0700	Booster Pump		.27				
1		**************************************	required minimus		2   Ye	s 🛭 No		
Was the chlorine residual ever less than the required minimum residual of 0.2 mg/L? Yes No  If yes, what was the longest time period until the required level was restored? hours								
	_		I	GWS Serving More Than 3,300				
If yes, did you monitor every four hours until the residual returned to 0.2 mg/L?  ☐ Yes ☐ No			Did continuous monitoring equipment fail at any time this reporting month?   Yes No			Date continuous monitoring equipment failed:		
Attach those results and submit them with			If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service?  Yes No			Date it was returned to service:		
this form.			Attach arah sar		ait thom wi	th this form	Service.	
Attach grab sample results and submit them with this form.								
Printed N	1/1	A	Title: Biller Mustice Tak Phone #: (328) 785-7235			Operator Certification #:		
Signature: Phone #: (328) 795-723 OR							OR	
Date: 1 1 3 1 2 Z Small Groundwater System □								